Private Aircraft



1980 Citation 1SP

1980 Citation 1SP



# **AIRFRAME:**

AFTT: 7,420 Total Landing Cycles: 7,419

## **ENGINES:**

ENGINE 1 SERIAL: PCE77162 Total Time Since New: 7,081 Since Overhaul: 638 Time Between Overhaul: 3,500 Total Cycles Since new: 7,272

## ENGINE 2

SERIAL: PCE77162 Total Time Since New: 7,189 Since Overhaul: 612 Time Between Overhaul: 3,500 Total Cycles Since new: 7,183

## **FEATURES**

Belted Lav CESCOM Thrust Reversers ADS-B Capable RVSM

## STANDARD EQUIPMENT

Traffic Collision Avoidance System Weather Radar Terrain Awareness & Warning System FM immunity Cockpit Voice Recorder

### AVIONICS

ADF: Dual Collins ADF-60A
Altimeter: IDC ADC-200 encoding w/alerter
Autopilot: Sperry SPZ-500 IFCS
Avionics Package: Sperry SPZ-500 IFCS/Pro Line
Communication Radios: Dual King KY-196B
Compass: Sperry C-14-43
DME: Dual Collins DME-40
Flight Director: Sperry SPZ-500 IFCS 5-inch single cue
GPS: King KLN-90B (IFR)
HSI: Collins PN-101
Navigation Radios: Dual Collins VIR-30A w/FM immunity
RMI: Dual RCA RMI-30
TCAS: None
Transponder: Garmin GTX-330D Mode S/Collins TDR-90
Weather Radar: Honeywell ART-2100 color

www.horizonoffshoreservices.com



#### ADDITIONAL EQUIPMENT

**Cockpit:** Honeywell KMD-540 multi-function display, Artex C406-1 ELT, Shadin air data computer, emergency horizon, Star Aviation air data system, angle of attack w/indexer, battery temperature monitor gauge, ADS-B Out

**Equipment**: Thrust reversers, 64 cubic foot oxygen system, 20-cell battery, engine fan/turbine synch, special C 560 brakes, engine fire extinguisher

Lights: Strobes

#### INTERIOR: Done in 2002

Configuration/PAX: Executive/7 passengers

General: Fire blocked

Seating: Beige leather seating, Belted lav seat

Carpet: Wool Carpeting

Lavatory: Yes

#### EXTERIOR: Done In 2002

Colors: Silver & Blue

#### MAINTENANCE

Maintained: FAR Part 91

Airframe Maint. Program: Unknown

Airframe Tracking Program: CESCOM

Certification(s): B-RNAV, RVSM

Engine Overhaul: By Volvo Aero Corporation, Sweden 2002

**Dam History Notes:** Aircraft experienced hard landing in 4/21/92 in Lugano, Switzerland; Repaired Hail damage 11/01; Repaired nose cone, leading edge & boots replaced.

www.horizonoffshoreservices.com

#### The offer for sale of this aircraft is subject to contract and the aircraft may at any time be withdrawn from the market without prior notice. Specification is always subject to verification by the purchaser.

#### alex.savov@horizonoffshoreservices.com & management@horizonoffshoreservices.com

**PRICE IDEA: \$599.000** 

# 1980 Citation 1SP









www.horizon off shores ervices.com

The offer for sale of this aircraft is subject to contract and the aircraft may at any time be withdrawn from the market without prior notice. Specification is always subject to verification by the purchaser.