

## **RECENT PHOTOGRAPHS: JULY-2023**



2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale




2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale



2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale






(72) Condition of No.3 cargo tank (P)




(69) Condition of No.3 cargo tank (P)




(67) Condition of No.2 cargo tank (S)



(66) Condition of No.2 cargo tank (S)




(64) Condition of No.2 cargo tank (S)




(60) Condition of No.2 cargo tank (P)



(56) Condition of No.2 cargo tank (P)



(52) Condition of No.1 cargo tank (S)



(51) Condition of No.1 cargo tank (S)




(46) Condition of No.1 cargo tank (S)



(45) Condition of No.1 cargo tank (S)



(42) Condition of No.1 cargo tank (P)



(41) Condition of No.1 cargo tank (P)



(39) Condition of No.1 cargo tank (P)

2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale






(30) The expansion deck for tank



(27) Condition of main deck & guardrails



(25) Condition of main deck



(22) Condition of mooring winch




(18) Condition of mooring bitts, fairlead rollers



(17) Chain locker

2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale



2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale




2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale




## 2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale



2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale





(68) Condition of No.2 cargo tank (S)



(65) Condition of No.2 cargo tank (S)



(62) Condition of No.2 cargo tank (S)



(59) Condition of No.2 cargo tank (P)



(47) Condition of No.1 cargo tank (S)

2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale






(32) Condition of pipe lines




(26) Condition of main deck




(20) Condition of poop deck

2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale



## 2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale






(63) Condition of No.2 cargo tank (S)



(61) Condition of No.2 cargo tank (S)




(58) Condition of No.2 cargo tank (P)



(57) Condition of No.2 cargo tank (P)



(55) Condition of No.2 cargo tank (P)




(50) Condition of No.1 cargo tank (S)



(40) Condition of No.1 cargo tank (P)

2004 / 3000 DWT / 88.12m Double Hull Oil/ Chemical Tanker Available for Sale





(29) The condition of catwalk